



March 27, 2009

Installing the 2200762 Replacement Guide Bar Rollers

This 2200762 Guide Roller Kit, replaces the original 2200760 hardware and the 2200765 rollers supplied with 2200RP, 4" x 106" Abrasive Belt Sanders built before March 2009. It also is the standard roller kit used on 2200RP units built after March 2009.

The new guide rollers are slightly larger than the original rollers. It is recommended that all five of the guide rollers be replaced at one time.

Below is a sketch showing the proper assembly of these rollers and hardware on to the 2200RP machines guide roller bar.

Note: The guide roller bar is not included with the 2200762-roller kit.

