
REMOVABLE MULLION INSTRUCTIONS MULLION INSTALLATION

- 1. FIELD NOTCH THRESHOLD AS SHOWN BELOW.
- 2. MOUNT TOP AND BOTTOM BRACKETS AS SHOWN.
- 3. CHECK MULLION FOR CORRECT LENGTH FROM BOTTOM OF MULLION TO CENTERLINE OF STRIKE.
 A. CUT BOTTOM IF NECESSARY.(CUSTOM OR W/O THRESHOLD.)
 B. CUT TO PROPER OVERALL LENGTH.
- 4. SLIP INTO TOP BRACKET, PICK-UP AND SWING INTO BOTTOM BRACKET, SET INTO PLACE ON TOP BRACKET, SECURE WITH BACK PLATES (SFF FIG. 42)



MULLION STABILIZER INSTALLATION

- 1. MOUNT MULLION PORTION TO MULLION AS SHOWN
- 2. CLOSE DOOR, POSITION DOOR PORTION AS SHOWN.
- 3. MARK HOLES, DRILL & TAP FOR 10-24 OVAL HEAD.

